



HICUR: High current measuring mode
bypass low current measuring circuit while
HICUR is high level.

HICUR=1: about +8.192A peak, 250uA/div
HICUR=0: about +81.92mA peak, 2.5uA/div

